

May 10, 1983

Mr. Meade A Stirland, Manager Environment, Health and Safety Anaconda Minerals Company New Mexico Operations P.O. Box 638 Grants, New Mexico 87020

Dear Mr. Stirland:

May 2, I inspected the Jackpile-Paguate Mine, Pueblo of Laguna Uranium Leases 1, 4 and 8. Erosion control berms along the Rio Paguate need to be repaired, especially around protore stockpile 10. Also, a gate in the North Paguate Pit was open, allowing access to water ponded in the pit bottom.

Please remember that inspection and maintenance of the berms along the Rio Paguate and all fences and gates were required by the District Mining Supervisor's instructions of January 22, 1982. Your continued compliance with those instructions will be appreciated.

Sincerely yours,

(ORIG. SGD.) GEORGE R. TETREAULT, JR.

cOR Herrick E. Hanks Rio Puerco Resource Area Manager

cc:

Area Director, Albuquerque Area Office, BIA Superintendent, Laguna Agency, BIA Governor, Pueblo of Laguna Nordhams, Haltom and Taylor Area Manager, Rio Puerco RA DMM-Mining

Inspection File: Laguna 1, 4 and 8

Mine Plan File: Anaconda Comprehensive Plan

Chron

017:DCJones: tt:5/10/83

POL-EPA01-0007029 CONFIDENTIAL